

## Defect Photo Report

<b>Region</b>	Northern Region
<b>Authority</b>	SANRAL
<b>Route</b>	R023
<b>Road ID</b>	R02302N

Thumbnail	Description
-----------	-------------



Structure ID - R023\_02N\_B1929  
 Structure Name - Road over Rail at Balfour  
 Road ID - R02302N  
 Photo Direction - E  
 Inspection Date - 2011-12-27  
 Description - DSCN3496.JPG apply protective coating to handrail and balustrade  
 Photo Number - S02



Structure ID - R023\_02N\_B1929  
 Structure Name - Road over Rail at Balfour  
 Road ID - R02302N  
 Photo Direction - W  
 Inspection Date - 2011-12-27  
 Description - DSCN3499.JPG missing guardrail on approaches  
 Photo Number - S04



Structure ID - R023\_02N\_B1929  
 Structure Name - Road over Rail at Balfour  
 Road ID - R02302N  
 Photo Direction - N  
 Inspection Date - 2011-12-27  
 Description - DSCN3504.JPG abutment leaks  
 Photo Number - S06

## Defect Photo Report

<b>Region</b>	Northern Region
<b>Authority</b>	SANRAL
<b>Route</b>	R023
<b>Road ID</b>	R02302N



Structure ID - R023\_02N\_B1929

Structure Name - Road over Rail at Balfour

Road ID - R02302N

Photo Direction - W

Inspection Date - 2011-12-27

Description - DSCN3497.JPG roadway joint

Photo Number - S03



Structure ID - R023\_02N\_B1929

Structure Name - Road over Rail at Balfour

Road ID - R02302N

Photo Direction - S

Inspection Date - 2011-12-27

Description - DSCN3494.JPG clear siltation

Photo Number - S00



Structure ID - R023\_02N\_B1929

Structure Name - Road over Rail at Balfour

Road ID - R02302N

Photo Direction - W

Inspection Date - 2011-12-27

Description - DSCN3495.JPG resurface deck

Photo Number - S01

## Defect Photo Report

<b>Region</b>	Northern Region
<b>Authority</b>	SANRAL
<b>Route</b>	R023
<b>Road ID</b>	R02302N

Structure ID - R023\_02N\_B1929

Structure Name - Road over Rail at Balfour

Road ID - R02302N

Photo Direction - N

Inspection Date - 2011-12-27

Description - DSCN3503.JPG abutment leaks

Photo Number - S05

